



## ST21 VF1J Full Armored Statue Assembly manual

## COMPONENTS OVERVIEW:





## LEFT LEG:

Components: #14, #15



Step 1a



Step 1b

## RIGHT LEG:

Components: #2, #7



Step 2a



Step 2b



Step 2c



Step 2d



## BACK PACK and Battery:

Components: #1




Step 3a: Insert LR44 Battery X2



Step 3b: Switch on the light up effect



Step 3c: Component #1



Step 3d

## LEFT ARM and ARMOR PART:

Components: #3, #16



Step 4a



Step 4b



Step 4c




Step 4d



## RIGHT ARM and ARMOR PART:


Components: #12, #13



Step 5a



Step 5b




Step 5c




Step 5d

## GUNPOD and LIGHT UP PART:


Components: GunPod and Light up Device



Step 6a: Open the cap of the gunpod. Take out the light up device.



Step 6b: Press the blue button to turn on the light



Step 6c: place the device back to the GunPod



Step 6d



## OTHER DIORAMA PARTS:

Components: #4, #5, #9




Step 7a: Component #4



Step 7b: Component #5



Step 7c: Component #9



Step 7d: Component #9

## OTHER DIORAMA PARTS:

Components: #8



Step 7e: Component #8



Step 7f: Done



## CHEST ARMOUR PARTS and ANTENNA:

Components: #6, #10, #11



Step 8a: Component #6



Step 8b



Step 8c: Component #10



Step 8d: Component #11

## USB CABLE and LIGHT UP FUNCTION:

Components: USB Cable from the base (Component #15)



Step 9:  
Plug the USB cable to power source to turn  
on the “breathing light” effect on the stand  
base